

# Eskada-M

## Veneered boards manufacturer №1

ESKADA·M  Veneered  
Boards Manufacturer №1

NOTHING BUT PERFECTION



ESKADA·M



Veneered  
Boards Manufacturer Ltd.

NOTHING BUT PERFECTION

## Our products:

- Veneered boards;
- Furniture elements.



592X96  
KOPETIK  
AMAPETTO-ITRACHIK  
(GOKKADU)  
BIRON O. AGIT 18 MM

Veneered board – is a board with a thin sheet/layer of natural wood. It is produced from a tree trunk in a numbers of ways.

ESKADA·M



Veneered  
Boards Manufacture

NOTHING BUT PERFECTION

We work with different types of veneer

ESKADA·M



Veneered  
Boards Manufacturer №1

NOTHING BUT PERFECTION

We specialized in Ukrainian series (beech,  
alder, ash, etc.)

White oak

White ash

Birch

Maple

Alder

Beech

Chipboard

Plywood


Blockboard

## MDF and water-resistant MDF

\*We highly recommended to use MR MDF in area with high humidity.



NOTHING BUT PERFECTION



**Fire-resistant plywood** certificated according to the European classification: B-S1, d0.  
B – Difficult to ignite;  
S1 – do not form smoke;  
d0 – do not form combustion products.



### Surface treatment:

- Lacquering;
- Oil and beeswax treatment;
- Staining;

**Fire-resistant:** we use oil and lacquer with adding of substances by Burnblock, which are organic and non-toxic.



ESKADA·M



Veneered  
Boards Manufacturer №1

NOTHING BUT PERFECTION

Touch Of Nature – created by nature





nd  
ign

Splint Walnut

Smoked  
Satin Walnut

ESKADA·M



Veneered  
Board Manufacturer

NOTHING BUT PERFECTION

Tineo





**CARE INSTRUCTIONS  
WIRE BASKET**

Apply linseed oil 4 times the first month and afterwards less time. It will close the surface and makes the top more resistant. Alternatively, use beeswax to treat and protect the surface. Never wipe with a damp cloth.

**CARE INSTRUCTIONS  
WIRE BASKET TOP**

Apply linseed oil 4 times the first month and afterwards less time. It will close the surface and makes the top more resistant. Alternatively, use beeswax to treat and protect the surface. Never wipe with a damp cloth.

Apply linseed oil 4 times the first month and afterwards less time. It will close the surface and makes the top more resistant. Alternatively, use beeswax to treat and protect the surface. Never wipe with a damp cloth.

Apply linseed oil 4 times the first month and afterwards less time. It will close the surface and makes the top more resistant. Alternatively, use beeswax to treat and protect the surface. Never wipe with a damp cloth.

Apply linseed oil 4 times the first month and afterwards less time. It will close the surface and makes the top more resistant. Alternatively, use beeswax to treat and protect the surface. Never wipe with a damp cloth.

Apply linseed oil 4 times the first month and afterwards less time. It will close the surface and makes the top more resistant. Alternatively, use beeswax to treat and protect the surface. Never wipe with a damp cloth.

Smoked oak can be determined by substance Y

**SMOKED OAK**  
Smoked oak can only be produced because of the substance tannin by nature. The natural tannin is determined by numerous factors such as climate, phase and by soil conditions.

The natural tannin content reacts during the smoking process and darkens the oak's surface therefore depends on the duration of the smoking and on the duration of the hand and on the variation of the smoked oak colour.



We are also produce a furniture elements (table cover and so on)



ABS edges

HPL Board

# Front




1180

1050


Plywood 25 mm  
Veneer - oak

MDF 25 mm




# Side

Plywood 25 mm  
Veneer - oak



Top

Plywood 25 mm  
Veneer - oak



Our options:

- edge banding;
- continuation of veneer texture;
- varnish coating;
- cut to size





## Pre-packed components

We can also deliver your components, sealed and packed on request



Veneered  
Boards Manufacturer №1

NOTHING BUT PERFECTION

We are always on hand to help you

